



2300 Orchard Parkway
San Jose, CA 95131-1017
Customer Assistance Center: 1-408-428-7907

FIELD SERVICE BULLETIN

FSB #: FSB 098-50620-048

DATE: July 11th, 2011

System: XL GPS Time and Frequency Receiver

Issue: Software Maintenance Release

Product Code:	Description
1530-602	XL GPS Time and Frequency Receiver

CLEI Code: N/A

Technical Support: Worldwide 1-408-428-7907 (1) (1) or USA toll free 1-888-367-7966

Customer Relations: Worldwide 1-408-428-7907 (2) (1) or USA toll free 1-888-367-

Summary

Changes from Project rev 2-0 to Project rev 2-2

1. Correcting of options cards intermittently not recognized by the CPU at power up.
2. The NTP alarm now clears when the XL GPS re-locks to a reference.
3. Filters out false alarms from Rubidium oscillators.
4. The application has Improved Oscillator control and estimation of time error during holdover via F13.
5. Correct problem of first TIET (Time Interval-Event Time) signal not being displayed on XL GPS front panel.

Recommended Actions: Customers with XL GPS, part number of 1530-602 are advised to Upgrade to Project rev 2-2

Long Term Solution: Upgrade to Project rev 2-2

Contact Information: E-mail technical support at: support@symmetricom.com

Symmetricom Inc
3750 Westwind Blvd
Santa Rosa CA 95403

Toll Free Calls: 888.367.7966 option 1, then option 2

Toll Calls: 408.428.7907 option 1, then option 2

<http://www.symmetricom.com>