

Issue Date: June 30, 2011

PDB Number: PDB_77KHz_LFR_Antenna.pdf

Product

Symmetricom, 77KHz LFR antenna.



Discontinued: 77KHz LFR antenna used with S300 and S350 Series SyncServers

Overview

Symmetricom is announcing the discontinuance of the 77KHz LFR antenna used with S300 and S350 SyncServers. All other variations of the LFR antenna (40KHZ and 60KHz) continue to be available.

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	No longer for sale
Extended Warranty Contracts (maximum expiration date)	Not applicable
Repair End Date (Out-of-warranty repairs will not be available for this product beyond this date)	Not applicable
Customer Support Contracts (non-repair services)	Not applicable

Affected Models and Replacement Product Summary

Current Models	Current Part #s	Replacement Models	Replacement Part #s
SyncServer 77.5 KHz LFR Kit (DCF77)	1520R-LFR77-KIT	No replacement	No replacement

Contact Information

Symmetricom Global Services: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide

Symmetricom Customer Service: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide
support@symmetricom.com
www.symmetricom.com

Government Business Unit: 3750 Westwind Blvd.
Santa Rosa, CA 95403
Telephone: 707-528-1230
Facsimile: 707-527-6640