

PRODUCT DISCONTINUANCE BULLETIN



Issue Date: March 7, 2003

PDB #:PDB_D_bc420-427VXI.doc

Product(s)

Datum Model bc420VXI RF Pulse Analyzer
Datum Model bc427VXI GPS RF Pulse Analyzer

Overview

Symmetricom is announcing the discontinuance of the Datum bc420/427VXI RF Pulse Analyzer. The bc420/427VXI has reached the end of its technology product lifecycle and the manufacturing of this product is being discontinued

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	June 7, 2003

Affected Models and Replacement Product Summary

Current Model	Current Part #	Replacement Model
Datum Model bc420VXI RF Pulse Analyzer	BC420VXI	none
Datum Model bc427VXI GPS RF Pulse Analyzer	BC427VXI	

Support Policy

Product support services (telephone technical support, on-site maintenance, training, spares support, etc.) and repairs are available from Symmetricom Global Services (SGS) on a contract or case-by-case basis. All services may not be available for every product. Interested customers should contact SGS to check a product's eligibility for services and any applicable terms.

Contact Information

Symmetricom Global Services 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide

Symmetricom Customer Service: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide
support@symmetricom.com
www.symmetricom.com

Timing, Test & Measurement Division: 3750 Westwind Blvd.
Santa Rosa, CA 95403
Telephone: 707-528-1230
Facsimile: 707-527-6640