

PRODUCT DISCONTINUANCE BULLETIN



Issue Date: December 4, 2007

PDB Number: PDB_GPS-605.pdf

Product

Symmetricom GPS-605 GPS Synchronized Clock and Time Code Generator



Overview

Symmetricom is announcing the discontinuance of the GPS-605 GPS Synchronized Clock and Time Code Generator.

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	March 10, 2008

Limited Availability Product Allocation

The GPS-605 is limited in availability due to a shortage of a key component. Orders during the discontinuance period will be limited to a quantity of three and may be allocated as product inventories are depleted.

Affected Models and Replacement Product Summary

Current Model	Current Part #'s	Replacement Model	Replacement Part #	Replacement Datasheet Link
GPS-605	820-501-000 820-501-006	XL-GPS Time & Frequency Receiver	1530-602	http://www.symmttm.com/pdf/Gps/DS_XL-GPS.pdf

Support Policy

Repair services will be available during the warranty period. For all out-of-warranty units, service options (repair, spares support, telephone technical support, on-site maintenance, training, etc.) will be available for 3 years after date of discontinuance. In the event of parts or component obsolescence, repairs will be made on a best effort basis. Interested customers should contact Symmetricom Global Services (SGS) to check a product's eligibility for services and any applicable terms.

Contact information...

Contact Information

Symmetricom Global Services

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide

Symmetricom Technical Service:

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide
support@symmetricom.com
www.symmetricom.com

Timing, Test & Measurement Division:

3750 Westwind Blvd.
Santa Rosa, CA 95403
Telephone: 707-528-1230
Facsimile: 707-527-6640