

PRODUCT DISCONTINUANCE BULLETIN



Issue Date: October 1, 2007

PDB Number: PDB_HIR.pdf

Product

Symmetricom High Isolation Repeater



Overview

Symmetricom is announcing the discontinuance of the High Isolation Repeater-Digital and High Isolation Repeater-Fiber.

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	December 31, 2007

Affected Models and Replacement Product Summary

Current Model	Current Part #'s	Replacement Model	Replacement Part #	Replacement Datasheet Link
HIR-Digital	144-751 144-752 144-753	NA	NA	NA
HIR-Fiber	144-754 144-755 144-756	NA	NA	NA

Support Policy

Repair services will be available during the warranty period. For all out-of-warranty units, service options (repair, spares support, telephone technical support, on-site maintenance, training, etc.) will be available for 4 years after date of discontinuance. In the event of parts or component obsolescence, repairs will be made on a best effort basis. Interested customers should contact Symmetricom Global Services (SGS) to check a product's eligibility for services and any applicable terms.

Contact information...

Contact Information

Symmetricom Global Services

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide

Symmetricom Customer Service:

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide
support@symmetricom.com
www.symmetricom.com

Timing, Test & Measurement Division:

3750 Westwind Blvd.
Santa Rosa, CA 95403
Telephone: 707-528-1230
Facsimile: 707-527-6640