

# SERVICE DISCONTINUANCE BULLETIN



Issue Date: July, 2006

PDB Number: PDB\_M100.Doc

## Product

Symmetricom, Model M100 Rubidium Oscillator



## Overview

Effective August 31, 2006, Symmetricom is discontinuing the service and support of all M100 Rubidium Oscillators and all associated options. The M100 is no longer economically affordable to support due to the overall age of the product and parts obsolescence.

Some of the key obsolescence issues are:

- Obsolete rubidium physics package material
- Obsolete Mil-Spec components
- Obsolete crystal resonators

We are no longer able to procure this material and therefore unable to offer repair services for the M100.

Symmetricom's 8130 Militarized Rubidium Oscillator is a functional replacement for the M100 offering improved functionality and performance. Below is a list of the M100 part numbers that can no longer be supported. The 8130 will replace most M100 versions listed below. Please consult the factory for details on specific 8130 model numbers and available options.

## Affected Models and Replacement Product Summary

Current Model	Current Part #'s		Replacement Model	Replacement Part #
M100	70502-1	70502-18	8130 8130LN	Consult factory for details on specific option requirements
	70502-8	70502-19		
	70502-9	70502-20		
	70502-10	70502-21		
	70502-11	70502-101		
	70502-12	70502-102		
	70502-13	70502-22		
	70502-14	70502-23		
	70502-14-2	70502-24		
	70502-17	70502-25		
		70502-26		

Contact information.....

**Contact Information**

Symmetricom Global Services

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA  
1-408-428-7907 worldwide select Option 1, then Option 2

Symmetricom Customer Service:

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA  
1-408-428-7907 worldwide select Option 2, then Option 2  
support@symmetricom.com  
www.symmetricom.com

Timing, Test & Measurement Division:

3750 Westwind Blvd.  
Santa Rosa, CA 95403  
Telephone: 707-528-1230  
Facsimile: 707-527-6640