

# PRODUCT DISCONTINUANCE BULLETIN



**Issue Date:** June 30, 2011

**PDB Number:** PDB\_SyncSwitch\_TC100.pdf

## Product

Symmetricom, SyncSwitch TC100 Transparent Clock/Managed Ethernet Switch



**Discontinued: SyncSwitch TC100**

## Overview

Symmetricom is announcing the discontinuance of the SyncSwitch TC100 Transparent Clock/Managed Ethernet Switch. This product has reached the end of its product lifecycle.

## Product Obsolescence Timeline

Milestone	Date
Last Day to Order	No longer available.
Extended Warranty Contracts (maximum expiration date)	Not applicable.
Repair End Date (Out-of-warranty repairs will not be available for this product)	July 1, 2011.
Customer Support Contracts (non-repair services)	Not applicable.

## Affected Models and Replacement Product Summary

Current Models	Current Part #s	Replacement Models	Replacement Part #s
SyncSwitch TC100, 10/100BaseT/TX	1550R-100	No replacement	No replacement
SyncSwitch TC100, Copper & MM Fiber	1550R-101	No replacement	No replacement
SyncSwitch TC100, Copper & SM Fiber	1550R-102	No replacement	No replacement

**Contact Information**

Symmetricom Global Services: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA  
1-408-428-7907 worldwide

Symmetricom Customer Service: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA  
1-408-428-7907 worldwide  
[support@symmetricom.com](mailto:support@symmetricom.com)  
[www.symmetricom.com](http://www.symmetricom.com)

Government Business Unit: 3750 Westwind Blvd.  
Santa Rosa, CA 95403  
Telephone: 707-528-1230  
Facsimile: 707-527-6640