

PRODUCT DISCONTINUANCE BULLETIN



Issue Date: October 31, 2005

PDB Number: PDB_5971A T1E1.Doc

Revised 2 February 2006 – Removed references to 5071a 48 Vdc option.

Product

Symmetricom, Model 5071A Primary Frequency Standard Telecom Options

Overview

Symmetricom is discontinuing the telecom output options for the 5071A Primary Frequency Standard. Symmetricom is replacing these options with similar configurations that are available on both the Cs4000 and the CsIII. The Cs4000 and CsIII will provide all the functionality previously available with the 5071A when configured with telecom outputs.

Please go to http://www.symmttm.com/products_precision_frequency_references.asp for detailed product information.

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	January 31, 2006

Affected Models and Replacement Product Summary

Current Model	Current Part #s	Replacement Model	Replacement Part #
5071A	Options	Cs4000	14645-110 (T1) 14645-135 (E1)
	048	CsIII	14534-XXX with option 13945-102 (T1) 13945-101 (E1)
	104		
	105		
	220		
	221		
	222		
	270		
	271		
	272		

Contact information.....

Support Policy

Repair services and maintenance contracts are expected to be until January 31, 2011. In the event of parts or component obsolescence, repairs will be made on a best efforts basis. All other service options (spares support, telephone technical support, on-site maintenance, training, etc.) are available from Symmetricom Global Services (SGS) on a contract or case-by-case basis. Interested customers should contact SGS to check a product's eligibility for services and any applicable terms.

Contact Information

Symmetricom Global Services 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide

Symmetricom Customer Service: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide
support@symmetricom.com
www.symmetricom.com

Timing, Test & Measurement Division: 3750 Westwind Blvd.
Santa Rosa, CA 95403
Telephone: 707-528-1230
Facsimile: 707-527-6640