

# PRODUCT DISCONTINUANCE BULLETIN



**Issue Date:** January 1, 2007

**PDB Number:** PDB\_6520.Doc

## Product

Symmetricom Model 6520A Telecom Distribution Amplifier



## Overview

Symmetricom is announcing the discontinuance of the Symmetricom Model 6520A Telecom Distribution Amplifier. The 6520A has reached the end of its technology product lifecycle and is being discontinued. There is no direct replacement for this product but similar functionality is available within Symmetricom. There are 7 units available for sale. There will be no additional units manufactured after the 7 units are depleted.

## Product Obsolescence Timeline

Milestone	Date
Last Day to Order	June 30, 2007

## Affected Models and Replacement Product Summary

Current Model	Current Part #'s	Replacement Model	Replacement Part #	Replacement Datasheet Link
6530A	14265-101 14265-102 14265-103 14265-104	None None None None	None None None None	

## Support Policy

Repair services will be available during the warranty period. For all out-of-warranty units, service options (repair, spares support, telephone technical support, on-site maintenance, training, etc.) will be available on a best efforts basis. Interested customers should contact Symmetricom Global Services (SGS) to check a product's eligibility for services and any applicable terms.

Contact information.....

**Contact Information**

Symmetricom Global Services

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA  
1-408-428-7907 worldwide

Symmetricom Customer Service:

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA  
1-408-428-7907 worldwide  
support@symmetricom.com  
www.symmetricom.com

Timing, Test & Measurement Division:

3750 Westwind Blvd.  
Santa Rosa, CA 95403  
Telephone: 707-528-1230  
Facsimile: 707-527-6640