

# PRODUCT DISCONTINUANCE BULLETIN



**Issue Date:** January 1, 2007

**PDB Number:**PDB\_6602B.Doc

## Product

Symmetricom Model 6602B Pulse Distribution Amplifier



## Overview

Symmetricom is announcing the discontinuance of the Symmetricom Model 6602B Pulse Distribution Amplifier. The 6602B has reached the end of its technology product lifecycle and is being discontinued. Symmetricom offers an improved and more feature rich replacement unit; model 4033A, that provides all the functionality of the 6602B along with the ability to distribute pulse rates from 1PPS- 1MPPS and IRIGB-DC and added features that include an Ethernet interface and 15 outputs.

## Product Obsolescence Timeline

Milestone	Date
Last Day to Order	June 30, 2007

## Affected Models and Replacement Product Summary

Current Model	Current Part #'s	Replacement Model	Replacement Part #	Replacement Datasheet Link
6602B	14369-101 SPCL-0009 SPCL-0010	4033A Contact factory Contact factory	4033A	

## Support Policy

Repair services will be available during the warranty period. For all out-of-warranty units, service options (repair, spares support, telephone technical support, on-site maintenance, training, etc.) will be available on a best efforts basis. Interested customers should contact Symmetricom Global Services (SGS) to check a product's eligibility for services and any applicable terms.

Contact information.....

**Contact Information**

Symmetricom Global Services

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA  
1-408-428-7907 worldwide

Symmetricom Customer Service:

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA  
1-408-428-7907 worldwide  
support@symmetricom.com  
www.symmetricom.com

Timing, Test & Measurement Division:

3750 Westwind Blvd.  
Santa Rosa, CA 95403  
Telephone: 707-528-1230  
Facsimile: 707-527-6640